
To: McClain-Vanderpool, Lisa[Mcclain-Vanderpool.Lisa@epa.gov]

From: Thomi, Wendy

Sent: Sat 8/8/2015 7:07:09 PM Subject: RE: Is this correct?



Thanks. Are you working on talking points for HQ or Press call?

Paula said she thought I could work on that.

From: McClain-Vanderpool, Lisa

Sent: Saturday, August 08, 2015 1:06 PM

To: Thomi, Wendy

Subject: RE: Is this correct?

He said both – first 1200 and that he thought it was more like 200. It's actually 587!

Lisa McClain-Vanderpool

Public Affairs Specialist/Media Officer

Office of Communications and Public Involvement

US Environmental Protection Agency, Region 8

1595 Wynkoop Street

Denver, Colorado 80202

Office 303.312.6077

Cell 303.501.4027

From: Thomi, Wendy

Sent: Saturday, August 08, 2015 12:46 PM

To: McClain-Vanderpool, Lisa **Subject:** RE: Is this correct?

Martin said 200 per minute, not 1200.

From: McClain-Vanderpool, Lisa

Sent: Saturday, August 08, 2015 12:45 PM

To: Thomi, Wendy

Subject: RE: Is this correct?

I think that was Martin's quote. Let's leave it.

Lisa McClain-Vanderpool

Public Affairs Specialist/Media Officer

Office of Communications and Public Involvement

US Environmental Protection Agency, Region 8

1595 Wynkoop Street

Denver, Colorado 80202

Office 303.312.6077

Cell 303.501.4027

From: Thomi, Wendy

Sent: Saturday, August 08, 2015 12:39 PM

To: McClain-Vanderpool, Lisa

Subject: Is this correct?

An acidic, yellowish discharge still was leaking out of the Gold King Mine portal, about 60 miles north of Durango (population 17,000), at an estimated rate of about 1,200 gallons a minute, state and federal officials said. EPA crews at the mine were trying to create a large hole to catch the contaminant-laced wastewater and try to clean it before it reaches streams and rivers.

Wendy Thomi, Brownfields Project Manager

U.S. EPA Region 8 Montana Office

10 W. 15th St.

Helena, MT 59626

Phone: 406-457-5037

Fax: 406-457-5056



Brownfields Information

http://www.epa.gov/brownfields